

de	Montageanleitung
en	Mounting instructions
fr	Instructions de montage
sv	Monteringsinstruktion
nl	Montage-aanwijzing
it	Istruzioni di montaggio
fi	Asennusohje
es	Instrucciones de montaje
da	Monteringsvejledning


Tauchtemperaturfühler
Immersion temperature sensor
Sonde de température à plongeur
Dykgivare
Dompeltemperatuuropnemer
Termosonda di mandata a immersione
Vesianturi
Sonda de temperatura de inmersión
Dykrørsføler

QAE3010...





QAE3075...



QAE3010...




QAE3075...



de Maßbilder
en Dimensions
fr Encombrements

sv Måttuppgifter
nl Maatschets
it Ingombri

fi	Mittapiirros
es	Dimensiones
da	Målskitse



Typ	A [mm]
QAE3010.010	100
QAE3010.016	160
QAE3075.010	100
QAE3075.016	160

Maße in mm
Dimensions in mm
Dimensions en mm
Mått i mm
Maten in mm
Dimensioni in mm
Mitat mm
Dimensiones en mm
Mål i mm