



| μF | RPN-0 RPC-0 | RPN-1 RPC-1 | RPN-2 RPC-2 | RPN-3 RPC-3 | RPN-6 RPC-6 |
|------|--------------------------------|--|--|---|---|
| | D x H mm | D x H mm | D x H mm | D x H mm | D x H mm |
| | 250 Vac B 25/085/21 (1+130 μF) | 360 Vac C 25/085/21 (1+80 μF) 250 Vac A 25/085/21 (1+80 μF) | 450 Vac C 25/085/21 (1+40 μF) 450 Vac C 25/070/21 (45+80 μF) 400 Vac B 25/085/21 (1+80 μF) | 500 Vac D 25/085/21 (1+70 μF) 450 Vac B 25/085/21 (1+70 μF) 400 Vac A 25/085/21 (1+70 μF) | 500 Vac C 25/085/21 (1+55 μF) 450 Vac 20000h 25/085/21 (1+55 μF) 400 Vac 50000h 25/085/21 (1+55 μF) |
| 2 | 28 x 56 | 28 x 56 | 28 x 56 | 28 x 56 | 28 x 56 |
| 2,5 | 28 x 56 | 28 x 56 | 28 x 56 | 28 x 56 | 28 x 56 |
| 3 | 28 x 56 | 28 x 56 | 28 x 56 | 28 x 56 | 28 x 56 |
| 3,15 | 28 x 56 | 28 x 56 | 28 x 56 | 28 x 56 | 28 x 56 |
| 3,5 | 28 x 56 | 28 x 56 | 28 x 56 | 28 x 56 | 32 x 56 |
| 4 | 28 x 56 | 28 x 56 | 28 x 56 | 28 x 56 | 32 x 56 |
| 4,5 | 28 x 56 | 28 x 56 | 28 x 56 | 28 x 56 | 32 x 56 |
| 5 | 28 x 56 | 28 x 56 | 28 x 56 | 32 x 56 | 32 x 56 |
| 6 | 28 x 56 | 28 x 56 | 28 x 56 | 32 x 56 | 36 x 58 |
| 6,3 | 28 x 56 | 32 x 56 | 32 x 56 | 32 x 56 | 36 x 58 |
| 6,8 | 28 x 56 | 32 x 56 | 32 x 56 | 36 x 58 | 36 x 70 |
| 7 | 28 x 56 | 32 x 56 | 32 x 56 | 36 x 58 | 36 x 70 |
| 7,5 | 28 x 56 | 32 x 56 | 32 x 56 | 36 x 58 | 36 x 70 |
| 8 | 28 x 56 | 32 x 56 | 32 x 56 | 36 x 58 | 36 x 70 |
| 9 | 32 x 56 | 36 x 58 | 36 x 58 | 36 x 70 | 36 x 70 |
| 10 | 32 x 56 | 36 x 58 | 36 x 58 | 36 x 70 | 40 x 68 |
| 11 | 32 x 56 | 36 x 58 | 36 x 58 | 36 x 70 | 40 x 68 |
| 12 | 32 x 56 | 36 x 70 | 36 x 70 | 36 x 70 | 40 x 68 |
| 12,5 | 36 x 58 | 36 x 70 | 36 x 70 | 40 x 68 | 40 x 93 |
| 13 | 36 x 58 | 36 x 70 | 36 x 70 | 40 x 68 | 40 x 93 |
| 13,5 | 36 x 58 | 36 x 70 | 36 x 70 | 40 x 68 | 40 x 93 |
| 14 | 36 x 58 | 36 x 70 | 36 x 70 | 40 x 68 | 40 x 93 |
| 15 | 36 x 58 | 36 x 70 | 36 x 70 | 40 x 68 | 40 x 93 |
| 16 | 36 x 58 | 36 x 70 | 36 x 70 | 40 x 68 | 40 x 93 |
| 17,5 | 36 x 70 | 40 x 68 | 40 x 68 | 40 x 93 | 40 x 93 |
| 18 | 36 x 70 | 40 x 68 | 40 x 68 | 40 x 93 | 40 x 93 |
| 20 | 36 x 70 | 40 x 68 | 40 x 68 | 40 x 93 | 45 x 93 |
| 25 | 40 x 68 | 40 x 93 | 40 x 93 | 45 x 93 | 50 x 93 |
| 30 | 40 x 68 | 40 x 93 | 40 x 93 | 45 x 93 | 50 x 93 |
| 32 | 40 x 93 | 40 x 93 | 40 x 93 | 50 x 93 | 50 x 93 |
| 35 | 40 x 93 | 45 x 93 | 45 x 93 | 50 x 93 | 50 x 118 |
| 40 | 40 x 93 | 45 x 93 | 45 x 93 | 50 x 93 | 50 x 118 |
| 45 | 40 x 93 | 50 x 93 | 50 x 93 | 50 x 118 | 55 x 122 |
| 50 | 45 x 93 | 50 x 93 | 50 x 93 | 50 x 118 | 55 x 122 |
| 55 | 45 x 93 | 50 x 93 | 50 x 93 | 50 x 118 | 60 x 122 |
| 60 | 45 x 93 | 50 x 118 | 50 x 118 | 55 x 122 | 60 x 122 |
| 65 | 50 x 93 | 50 x 118 | 50 x 118 | 55 x 122 | |
| 70 | 50 x 93 | 50 x 118 | 50 x 118 | 60 x 122 | |
| 75 | 50 x 93 | 50 x 118 | 50 x 118 | 60 x 122 | |
| 80 | 50 x 93 | 55 x 122 | 55 x 122 | 60 x 122 | |
| 90 | 50 x 118 | 55 x 122 | 55 x 122 | | |
| 100 | 50 x 118 | 60 x 122 | 60 x 122 | | |
| 130 | 55 x 122 | | | | |